

1. T-G Bearing T13 (generator steady bearing)- Resolve no oil flow condition out bearing drain to local wier.
  - a. roll out bearing, inspect assembly and bearing condition
2. Secondary Air Heater 1B- Identify and resolve high amps (7 amps high after startup 7 amps, presently down to 3 amps) and 2 different rubs sources. One rub source coming from gearbox engagement and the other coming from hot end bypass seals.
  - a. inspect and resolve interference problems
  - b. replace any ripped out seals
3. Burners O/S- Replace diffusers and nozzles (if required) on E4 and A4 burners which are isolated due to burner fires.
  - a. remove elbows and replace diffusers (and nozzles?)
  - b. restore isolation back to normal
4. Windbox Secondary Air Damper 1H- There is a 12 degree difference on blade pitch between east and west dampers.
  - a. adjust linkage and blade pitch and verify position
5. Windbox Dampers- Stroke all dampers and repair those that are hanging up.
  - a. stroke dampers to identify LVDT's and cams that may be hanging up.
6. Burner Thermocouples- Repair or replace ?? bad backplate and nozzle thermocouples for out of service temperature control and burner line fire indication.
  - a. repair or replace bad T/C's
7. Burner Line Restrictors- Complete changeout of D coal restrictors (2) that were not completed during the Spring Outage. Should not require asbestos abatement. (Pulv B, C, E, F, G & H however will require abatement).
8. Boiler Feed Pump 1B- High inboard pump vibration.
  - a. install new coupling bolts (spare set in warehouse)
  - b. install key phase reference
9. Burner Inspection- East to west air flow inbalance.
  - a. inspect all dampers, air registers and duct work to see if there are any physical obstructions to air flow
10. Boiler Inspection- Air flow imbalances.
  - a. inspect all expansion joints and casings for potential air in-leakages effeccting air flow
11. Instrumentation Calibrations-
  - a. Air foils, East and West sides
  - b. FD fan air flows (1A and 1B)